कार्यालय कार्यपालन यंत्री, लोक निर्माण विभाग, संभाग क्रं.—1 ग्वालियर ☎0751-2371231, Email: eepwd1gwl@mp.nic.ln

क्रमांक 4037/तकनीकी /भवन सुरक्षा प्रमाण-पत्र / 2022-23 ग्वालियर दिनांक : ५\१\ 23

प्रति,

रांयुक्त संचालक लोक शिक्षण संभाग ग्वालियर।

विषय:- भवन सुरक्षा प्रमाण-पत्र जारी करने के सम्बंध में।

सन्दर्भ :- आपका कार्यालयीन पत्र क्रं./मान्यता/भा.सु.प्र.प./2023-24/2475 ग्वालियर दिनांक 20.06.2023

विषयान्तर्गत सन्दर्भित पत्र के तारतम्य में लेख है कि आपके द्वारा चाहा गया सरस्वती शिशु मंदिर केदारपुर, शिवपुरी लिंक रोड़ ग्वालियर के भवन का सुरक्षा प्रमाण–पत्र आपकी ओर आवश्यक कार्यवाही हेतु संलग्न प्रेपित है। सहपत्र :- भवन सुरक्षा प्रमाण–पत्र।

कार्यपालन यंत्री लोक निर्माण विभाग संभाग क्रं.–1 ग्वालियर

BUILDING SAFETY CERTIFICATE

No. 4037

Dated: 64/67/23

Certified that the existing building SARASWATI SHISHU MANDIR KEDARPUR at Shivpuri Link Road Kedarpur, Gwalior (M.P.) Comprised of Ground Floor and First Floor, Second Floor owned/occupied by SARASWATI SHISHU MANDIR KEDARPUR Shivpuri Link Road Kedarpur, Gwalior (M.P.) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of M.P.P.W.D. Division Gwalior (M.P.) on 27.06.2023 in the presence of Principal of Principal Mr. Amit Kumar Shrivastava SARASWATI SHISHU MANDIR KEDARPUR, Shivpuri Link Road Kedarpur, Gwalior (M.P.) and that the building/premises is fit for occupancy up to classes XIIth. With effect for 2023-24 for a period of one years in accordance with rule and subject to compliance of the specific condition appended.

Sub Engineer

PWD Road sub Division

Assistant Engineer

PWD Road subdivision Gwalior

Executive Engineer

PWD Division No.1 Gwalior